This Page Is Inserted by IFW Operations and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.

	Туре	Ľ #	Hits	Search Text	DBs	Time Stamp	Comment	Error Definition	R C H
Щ	BRS	Ľ1	8 N	(ambula\$ wheelchair handicap\$) and ((wheel with caster) with (adjust\$ mov\$ slid\$)) and (rail handle) and sleeve and (ramp surface)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/20 17:18			0
Ν	BRS	L ₂	2 8	5/81.1RP.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/20 17:32			0
ω	BRS	L ₃	92	5/81.1HS.ccls.	UB; PO; PT;	2004/05/20 17:54			0
4	BRS	L4	231	5/81.1R.ccls. and (wheel caster)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/20 17:34			0
ហ	BRS	L ₅	163	5/81.1R.ccls. and (wheel caster) and (handle rail handlebar)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/20 17:37			0
Ø	BRS	L6	4 4	5/81.1R.ccls. and ((wheel caster) with verticals) and (handle rail handlebar)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/20 17:38			0
7	BRS	L7	22	5/\$.ccls. and ((wheel caster) with vertical\$) and (handle rail handlebar) and (ramp)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/20 17:50			

ু প্ৰাপ্ত ক্ৰমুখিক চেটু বঁঞ্জন কুনুষ্টাৰ **পাৰ্ট প**ৰেছিল

A THE MARKET AND A CALLED BY THE SECOND

	Туре	₽ #	Hits	Search Text	DBs	Time Stamp	Comment	Error Definition
ω	BRS	L8	41	((wheel caster) with vertical\$) and ((handle rail handlebar) same (sleeve)) and (incline\$ with ramp)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/20 17:51		
	BRS	Г9	2 8	5/81.1rp.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/20 17:59		
10	BRS	L10	10	2975435.URPN.	USPAT	2004/05/20 17:57		
11	BRS	L 1 1	454 454	5/86.1.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/20 18:09		
12	BRS	L12	519	(14/\$.ccls. 5/\$.ccls.) and (vertical\$ with (caster wheel))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/20 18:10		
13	BRS	L13	ស ភ ភ	(14/\$.ccls.) and 5/\$.ccls.) and (vertical\$ with (mov\$ adjust\$) with (caster wheel))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/20 18:18		
14	BRS	L14	124	(14/\$.ccls. 5/\$.ccls.) and ((foot with pedal) same (caster wheel))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/20 18:35		

	Type	ተ #	Hits	Search Text	DBs	Time Stamp	Comment	Error Definition
D D	BRS	L15	144	(14/\$.ccls.) and (foot 5/\$.ccls.) and (foot with (lever actuator pedal) same (caster wheel)) and (handrail rail\$ handle	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/20		
16	BRS	L16	562	(ramp dolly wheelchair) and (foot with (lever actuator pedal) same (caster wheel))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/20		
17	BRS	L17	18	(ramp dolly wheelchair) and (foot with (lever actuator pedal) same (caster adj wheel))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/20		
H &	BRS	L18	N	4793445.pn.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/20 19:40		
19	BRS	L19	Q	4793445 _, URPN.	USPAT	2004/05/20 19:41		***************************************
20	BRS	L20	21	(foot with (lever actuator pedal) same (caster adj wheel) same (rais\$ and lower\$))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/20 19:43		
21	BRS	L23	11	4922560.URPN.	USPAT	2004/05/20 19:52		

Ty	Type L	#	Hits	Search Text	DBs	Time Stamp	Comment	Error Definition	r o r
22 BRS	s L2	4	17	("2582143" "2878078" "3757388" "2878078" "3085258" "3259427" "3272530" "3591874" "3438642" "4279043" "4157593" "4279043" "4474202" "4491193" "4510633" "4763756").PN.	USPAT	2004/05 ⁻ /20 19:52			0
23 BRS	S L2	σ	28	4314576.URPN.	USPAT	2004/05/20 19:54		***************************************	0
24 BRS	S L2	ω	7	("2757388" "2792874" "3158398" "3354893" "3398974" "3477673").PN.	USPAT	2004/05/20			0
25 BRS	s L2	v	18	3591874.URPN.	USPAT	2004/05/20 19:57		***************************************	0
26 BRS	S L3	N	16	3272530.URPN.	USPAT	2004/05/20 19:58			0
27 BRS	S L	Л	17	("2596055" "3272530" "47111445" "4314576" "4844107" "4948156" "4964182" "4987622" "4987622" "5086798" "5188139" "5226439").PN.	USPAT	2004/05/20 19:59			0
28 BRS	S L3	م	7	5449013.URPN.	USPAT	2004/05/20 19:59		***************************************	0

子言写图: (B) (A) 2006年(数)。

	Туре	۲ #	Hits	Search Text	DBs	Time Stamp	Comment	Error Definition	は、ないま
29	BRS	L37	Ø	(inclin\$ with ramp) and ambulance and (caster wheels)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/20 20:01			0
30	BRS	L38	72	(ramp) and ambulance and (caster wheel)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/20 20:04			0
ωμ	BRS	L39	Д 4	(incline\$ with ramp) and (caster with wheel) and (sleeve same (rail handle handlebar railing handrail))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/20 20:05			0
3 22	BRS	L40	14	(incline\$ with ramp) and (caster with wheel) and (sleeve same (rail handle handlebar railing handrail))	USOCR	2004/05/20 20:06			0
ω ω	BRS	L41	183	(incline\$ with ramp) and (wheel) and (sleeve same (rail handle handlebar railing handrail))	USOCR	2004/05/20 20:07			0
3 4	BRS	L42	183	(incline\$ with ramp) and (wheel) and (sleeve same (rail handle handlebar railing handrail))	USOCR	2004/05/20 20:09			0
დ თ	BRS	L43	130	(incline\$ with ramp) and (wheel) and (sleeve same (rail handle handlebar railing handrail))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/20 20:11			0

医二甲甲酰胺 医甲甲氏病 化光光谱 医水流 化二氯二苯甲基甲酚 克尔马克斯斯斯 医牙孔炎

40	ω 9	ω	37	ω 6	
BRS	BRS	BRS	BRS	BRS	Ϋ́T
					Туре
LÝ9	L48	L47	L46	L45	#
75	ហ ហ	Н	ហ	14	Hits
14/72.5.ccls.	(incline\$ with ramp) and (wheel) and (rail handle handlebar railing handrail) and handicapped	(incline\$ with ramp) and (wheel) and (rail handle handlebar railing handrail) and handicapped	(incline\$ with ramp) and (wheel) and (rail handle handlebar railing handrail) and invalid	ramp) (rail r l) and	ch Text
USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	USOCR	USOCR	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	DBs
2004/05/20 20:29	2004/05/20 20:29	2004/05/20 20:19	2004/05/20 20:18	2004/05/20 20:18	Time Stamp
					Comment
					Error Definition
0	. 0	0	0	0	r o r

in the second the second second in the second

ω	, N	H	
₩	B	m	
พิ พ	S	BRS	Type
ω ω	4 1	76	Hits
("5435028" "5231721" "5257426" "4279043" "3911509" "5354022" "5347666" "5507044" "5579864" "4550802") and (wheel caster) and (rail handle)	("5435028" "5231721" "5257426" "4279043" "3911509" "5354022" "5347666" "5507044" "5579864" "4550802") and (wheel caster)	"5435028" "5231721" "5257426" "4279043" "3911509" "5354022" "53547666" "5347666" "5579864" "4550802"	Search Text
USPAT	USPAT	USPAT	DBs
2004/05/20 14:21	2004/05/20 14:21 2004/05/20		
	·		Comments
			Error Definition

USPAT 2004/05/20 14:24 USPAT; US-PGPUB; 2004/05/20 EPO; JPO; 17:17	_MGI	_MGI	US. EPO DEI	(ambula\$ wheelchair handicap\$) and (wheel with caster) and (rail handle) and sleeve and (ramp surface)	198	BRS BRS	7 0
-		004/05/	USPAT	("3591874" "4314576" "4843661" "4894871" "5226439" "5295498" "5347666" "5435028" "5499645" "5509152" "5787515" "5794284" "5950258" "5983911").PN.	18	BRS	U
		2004/05/20 14:26	USPAT	("5435028" "5231721" "5257426" "4279043" "3911509" "5354022" "5347666" "557044" "5579864" "4550802") and (wheel caster) and (rail handle)	ω ω	BRS	4
Error Definition	Comments	Time Stamp	DBs	Search Text	Hits	Туре	

The state of the s

7	0	ហ	4	
0	0	0		Errors

The transfer of the state of th

.

.